

LIST of S C H I R T FACTORY MACHINES:

Quantity - mc type / model number /	number of picture
1 pc spreading table 12 x 1,80 m + 6 x 1,80 - + 1 ps Bullmer Spreading automat-KO-11-S30	1-7
1 pc Adler (front lath)buttonhole mc .tyyp.1962-1	8
1 " Adler buttonhole.autom.	9-13
1 " Adler (front lath 2 needel with buller feed.	18
1 " Dyrkopp " " " " 741-26-27	14-16
2 " " " " buttonhole mc 556-1101	34-35-36-37
1 " " " " " long seam autom. 576-1111	74-75-76
2 " Adler pocket semi automat - 961-23-4-0 - pls see ca 40 pcs different pocketform,and diff. sizes for mens and womens production.	77-84
1 " Union Special 1 needle chainstich ms XF 511H	22+27
1 " " " 39500 W owerlock mc	38-39
3 " Dyrkopp button sewing mc 3306-001	37-
1 " Dyrkopp 1 needle lockstich mc	17-
3 " Dyrkopp/Adler 1 + 2 needle mc	23-24-25-26
1 " Adler collar & cuf cutting mc 1963-1	44-45-46
4 " Stecko fastener press autom.	96-97-98-99
1 " EWA REX glue press for collar / cuffs	19-21
2 " PMM cutting mc for collar	40-41-42-43
1 " Kannekiesser H 600 clue press for collat /cufs	47-48-49-50
5 " Gygli Tech top fusing mod pre 5 / 60	51-52-53-54 55-56-57
1 " Kannekiesser front pice press	58-59
1 " PONY steam puppet	60-64
2 " Kannekiesser XVK press mc	65-66-67
1 " ERWO " "	68-69-70
2 " steam ironing tables	71-72-73
2 " Kannekiesser + Gygli Glue press	85-
- several pcs different spareparts mc	86-95
- " " " " " "	100-110